LG V10 Vibrator Replacement

This video shows you how to change the vibrator of LG v10.

Written By: Eric



INTRODUCTION

https://www.youtube.com/watch?v=p2UirXlu...

[video: https://www.youtube.com/watch?v=p2UirXlumxk]

If your lg v10 can not vibrator in any conditions or the vibration causes noise, you should change the vibrator. Follow this video to fix the problem.

TOOLS:

- Tweezers (1)
- Spudger (1)

PARTS:

- LG V10 vibrator (1)

Step1 Remove back cover and battery;

Step2 Remove back frame and motherboard;

Step3 Remove the broken vibrator;

Step4 Install a new vibrator;

Step5 Install motherboard and back frame;

Step6 Test the new vibrator;

Step7 Fasten screws and back cover.

This document was last generated on 2017-08-30 06:04:40 AM.